PlateSpin Portability Suite 8.1.3 Release Notes

February 16, 2010

Novell®

1 About This Release

These release notes apply to both PlateSpin® Migrate and PlateSpin Protect.

PlateSpin Portability Suite version 8.1.3 is the follow-on release after version 8.1.2. It features improved driver support for Dell*, HP*, Fujitsu*, and Cisco* UCS systems, functional enhancements, and a list of bug fixes.

For information about previous 8.1.x releases, see the *Previous Releases* section on the PlateSpin Portability Suite documentation Web site (http://www.novell.com/documentation/platespin_portabilitysuite_810).

2 New Features in this Release

- Section 2.1, "Enhanced Support for Dell, HP, Fujitsu, and Cisco UCS Targets," on page 1
- Section 2.2, "Enhanced Support for VMware ESX 4," on page 1

2.1 Enhanced Support for Dell, HP, Fujitsu, and Cisco UCS Targets

This release features updated drivers to better support workload migrations to Dell, HP, Fujitsu, and Cisco UCS hardware. In addition, you can now use a unique, specific ISO boot image for the following hardware types:

- Dell
- Fuiitsu
- Cisco UCS

The boot images are available for download from either Novell® or PlateSpin download sites.

2.2 Enhanced Support for VMware ESX 4

This release features support for creating eagerzeroedthick virtual disks on VMware* ESX* 4.

To enable this feature, go to your Portability Suite Server host. In the ..\PlateSpin Portability Suite Server\Web directory, open the Web.config file with a text editor, locate the CreateEagerZeroedThickDisksForESX4 attribute, and change its value to true. When you have finished, save and close the Web.config file.

NOTE: Enabling this feature causes a significant increase in the time it takes to create the target VM. For example, creating a VM with an 80 GB virtual disk might take approximately 20 to 30 minutes.

3 Bug Fixes

The following is a list of bugs fixed for this release.

- 565286 Missing system volume information in image capture jobs: System volume information is now properly captured for some Windows* 2000 systems, resulting in a No system volume included error.
- 555880 Slow job response in migrations to vCenter-affiliated ESX servers: Attempting to set up a migration job to an ESX server managed by a heavily loaded vCenter* no longer results in degraded client performance.
- Failure to preserve drive letters of removable devices: When migrating or protecting a workload with removable devices (such as a floppy disk or a CD-ROM drive), the respective drive letters are now preserved upon booting in the target environment.
- Improper handling of network connection names: When migrating or protecting Windows workloads, network connections associated with real network interfaces no longer default to Windows Standard names. For example, My Custom Network Connection no longer becomes Network Connection 2 in the target environment.
- Configuration Service failing to load on a heavily loaded VM: When under extreme load, Windows failed to start the PlateSpin Configuration Service in the time allotted. The fix introduced in this release includes the capability to delay the start of the Configuration Service until the load on the host is more favorable.

NOTE: Use this procedure only if you encounter this problem.

To activate the feature, go to your Portability Suite Server host. In the ..\PlateSpin Portability Suite Server\Web directory, open the Web.config file with a text editor, locate the delayConfigServiceStart attribute, and change its value to true. When you have finished, save and close the Web.config file.

- Failure to assign volume drive letters after a Restore or a Test Restore job: This issue, although it was unreproducible in-house, has beed addressed.
- Failures in restoring WMI during a Restore or a Test Restore job: Occasionally, when under load, WMI failed to load properly on the target servers. This issue has been addressed by changes in how VMware Tools are installed and when reboots are performed during the configuration process.
- Failure to install VMware Tools on specific systems: In some cases, the VSS component of VMware Tools conflicted with other software packages installed on specific workloads. The fix introduced in this release includes the capability to automatically skip the installation of the VSS component when migrating an affected workload into a VMware environment.
 - To activate the feature, go to your Portability Suite Server host. In the ...\PlateSpin Portability Suite Server\Web directory, open the Web.config file with a text editor, locate the ConfigService.VMWareToolsInstallRuntimeParameters attribute, and change its value to REMOVE=VSS. When you have finished, save and close the Web.config file.
- Erroneous report of VMware installation failure: When under extreme load, the VMware Tools installation step no longer reports a failure when it is actually successful.
- Restore and Test Restore Jobs occasionally stalling under load: When under extreme load, Restore and Test Restore jobs no longer stall without any error or warning.

- 527302 Incorrect job step labels when migrating into Citrix XenServer 5.5: In the Jobs view, some substeps of a migration job into a Citrix* XenServer* 5.5 target are no longer labeled *Unknown* or *Not Started* despite the migration running successfully.
- 568103 Failure to run the Image Operations tool on 64-bit Windows systems: A packaging issue caused the Image Operations tool (ImageOperations.exe) to fail to start on a 64-bit Windows environment. Going forward, the tool is supported on both 32-bit and 64-bit Windows platforms.
- Scalability issues when working with heavily loaded ESX servers: When migrating or
 protecting workloads to ESX servers that were under extreme load, the product occasionally
 ran into intermittent issues, affecting the ability of the jobs to complete. This release includes a
 number of fixes that address this scenario.

4 Known Issues

No new known issues have been logged as of the time of this release.

For a cumulative list of known issues logged since the 8.1 release, see the previous release notes:

Portability Suite 8.1.2 Release Notes (http://www.novell.com/documentation/platespin_portabilitysuite_810/readme/data/readme_812.html).

5 Documentation Conventions

In Novell documentation, a greater-than symbol (>) is used to separate actions within a step and items in a cross-reference path.

A trademark symbol (®, TM, etc.) denotes a Novell trademark; an asterisk (*) denotes a third-party trademark

6 Legal Notices

Novell, Inc. makes no representations or warranties with respect to the contents or use of this documentation, and specifically disclaims any express or implied warranties of merchantability or fitness for any particular purpose. Further, Novell, Inc. reserves the right to revise this publication and to make changes to its content, at any time, without obligation to notify any person or entity of such revisions or changes.

Further, Novell, Inc. makes no representations or warranties with respect to any software, and specifically disclaims any express or implied warranties of merchantability or fitness for any particular purpose. Further, Novell, Inc. reserves the right to make changes to any and all parts of Novell software, at any time, without any obligation to notify any person or entity of such changes.

Any products or technical information provided under this Agreement may be subject to U.S. export controls and the trade laws of other countries. You agree to comply with all export control regulations and to obtain any required licenses or classification to export, re-export, or import deliverables. You agree not to export or re-export to entities on the current U.S. export exclusion lists or to any embargoed or terrorist countries as specified in the U.S. export laws. You agree to not use deliverables for prohibited nuclear, missile, or chemical biological weaponry end uses. Please refer to the Novell International Trade Services Web page (http://www.novell.com/info/exports/) for more information on exporting Novell software. Novell assumes no responsibility for your failure to obtain any necessary export approvals.

Copyright © 2009 Novell, Inc. All rights reserved. No part of this publication may be reproduced, photocopied, stored on a retrieval system, or transmitted without the express written consent of the publisher.

Novell, Inc. has intellectual property rights relating to technology embodied in the product that is described in this document. In particular, and without limitation, these intellectual property rights may include one or more of the U.S. patents listed on the Novell Legal Patents Web page (http://www.novell.com/company/legal/patents/) and one or more additional patents or pending patent applications in the U.S. and in other countries.

For Novell trademarks, see the Novell Trademark and Service Mark list (http://www.novell.com/company/legal/trademarks/tmlist.html).

All third-party trademarks are the property of their respective owners.